

temperature indicators



TEMPERATURE INDICATORS

CODE OF PRODUCT	MEASUREMENT RANGE (° C)
1	37,8 °C - 77 °C
1A	54,4 °C - 104 °C
2	82 °C - 132 °C
2A	110 °C - 160 °C
3	138 °C - 188 °C
3A	166 °C - 216 °C
4	193 °C - 254 °C
4A	199 °C - 260 °C

* For verification of the existing thermometers used in ovens.

* For checking whether the product left in an oven reaches the required temperature.

* For following up the critical machine part applications (Bearing journals, Electric motors etc.)

* Temperature measurement labels; They are fast measurement labels that can be used in paint processes, electronics industry, detection of machine malfunctions.

* Ease of use, quick and precise measurement.

* Indicators formulas accurate to $\pm 1\%$

* Reaction time is about 1 - 3 seconds.